

DEC 1 1982

Department of Justice
 Wisconsin Regional Crime Lab
 ATTN: John P. Buck, Section Leader
 15725 W. Ryerson Road
 New Berlin, WI 53151

License No. 48-17508-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on November 8, 1982, of activities authorized by NRC Byproduct Material License No. 48-17508-01 and to the discussion of our findings with you and Mr. J. Oehldrich at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,



D. G. Wiedeman, Chief
 Materials Radiation Protection
 Section 1

Enclosure: Appendix,
 Notice of Violation

cc w/encl:
 DMB/Document Control Desk (RIDS)

RIII 
 Burgin/jp
 11/22/82

RIII 
 Wiedeman
 12/1/82

IE HQ FILE COPY

8212080454 821201
 NMS LIC30
 48-17508-01 PDR

DMB: IE 07