

APPENDIX A

NOTICE OF VIOLATION

Entergy Operations, Inc.
Arkansas Nuclear One

Dockets: 50-313
50-368
Licenses: DPR-51
NPF-6

During an NRC inspection conducted on March 20 through April 30, 1994, two violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violations are listed below:

- A. Technical Specification 6.8.1 states, in part, written procedures shall be established, implemented, and maintained covering the activities referenced in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Section 3.f.(1) of Appendix A to Regulatory Guide 1.33, Revision 2, February 1978 states, in part, that instructions for changing modes of operation should be prepared as appropriate for maintaining containment integrity.

Attachment C of Procedure 2102.001, "Plant Preheatup and Precritical Checklist," requires items in the containment building to be secured or, if they are to remain in the building, that the items be evaluated for their effect on plant operation.

Contrary to the above, on April 18, 1994, items such as ropes and instrumentation cables were neither evaluated for their effect on plant operation nor secured in the containment building.

This is a Severity Level IV violation. (Supplement I) (368/9404-02)

- B. 10 CFR Part 50, Appendix B, Criterion V, states, in part, that activities affecting quality be accomplished in accordance with instructions.

Procedure 6030.007, Revision 0, dated March 31, 1993, "Control of Plant Modifications Welding," Step 6.1.5, requires that uncalibrated ammeters used to perform welding machine amperage checks be verified with a calibrated ammeter at least once per month and that a log of all uncalibrated meters in use be documented.

Contrary to the above, as of April 5, 1994, uncalibrated ammeter checks have not been performed and logged.

This constitutes a Severity Level IV violation. (Supplement I)
(313/9404-04; 368/9404-04)

Pursuant to the provisions of 10 CFR 2.201, Entergy Operations, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear

with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,
this *20th* day of *June* 1994