

APPENDIX

NOTICE OF VIOLATION

Department of the Air Force
Brooks AFB, Texas 78235-5217

Docket: 030-28641
License: 42-23539-01AF

During an NRC inspection conducted on May 18-20, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

10 CFR 35.50(b)(3) requires, in part, that a licensee test each dose calibrator for linearity over the range of its use between the highest dosage that will be administered to a patient and 10 microcuries.

Contrary to the above, the licensee's dose calibrator linearity tests performed on October 7, August 2, April 2, and January 5, 1993, and April 6, 1994, were not tested over a range that extended to the lower limit of 10 microcuries.

This is Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, the Department of the Air Force, Brooks AFB, is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas
this 21st day of June 1994

9406280022 940621
PDR ADOCK 03028641
C PDR

bcc:
 DMB - Original (IE-07)
 LJCallan
 SJCollins
 RAScarano
 DWeiss, OC/LFDCB (T-9E10)
 *WLFisher
 *CLCain
 *FAWenslawski
 *GLGuerra
 *MLMcLean
 *NMIB
 *MIS System
 *RIV Files (2)
 SLMerchant, NMSS (T-8F5) w/QMP Field Notes

 *W/IFS Form

RIV:NMIB	NMIB	AC:NMIB <i>etc</i>	DD:DRSS <i>ipid</i>	D:DRSS <i>ipid</i>
*GLGuerra	*MLMcLean	CLCain	RAScarano	SJCollins <i>ipid</i>
05/ /94	05/ /94	06/15/94	06/21/94	06/21/94

*Previously concurred

INSPECTION FOLLOW-UP SYSTEM REPORT NUMBER 6
 LICENSEE VIOLATION REPORT - REGION: 4
 SORTED BY ITEM SEQUENCE

LICENSEE: AIR FORCE, DEPARTMENT OF THE
 LICENSE #: 42-23539-01AF

030-28641

TRANSMITTAL DATE: 02/11/1994
 LEAD INSPECTOR: M2M
 REPORT #: 93-010

SEQUENCE	ITEM TYPE	SEV / SPL	10CFR / LC / TD	EA NUMBER	STS	CLOSEOUT	TITLE
01	VIO	3 / 4	10 CFR: 1020 207	93- 313	-0	Closed	FAILURE TO SECURE BYPRODUCT MATERIAL
			ITEM COMMENT TEXT:				10 CFR 20.207 (A) REQUIRES THAT LICENSED MATERIALS STORED IN AN UNRESTRICTED AREA BE SECURED AGAINST UNAUTHORIZED REMOVAL FROM THE PLACE OF STORAGE. 10 CFR 20.207 (B) REQUIRES THAT LICENSED M
02	VIO	4 / 4	LIC COND: LCZZ		-0	Closed	FAIL. TO INCLD. REQUIREMENT F/PHYSICAL INVNTY.F/P
			ITEM COMMENT TEXT:				LICENSE CONDITION 16 STATES, IN PART, THAT THE LICENSEE SHALL ADHERE TO STATEMENTS AND REPRESENTATIONS CONTAINED IN THE APPLICATION DATED APRIL 12, 1985. SECTION 10.D OF THE APPLICATION STATE

Above items closed on inspection report 94-05

GL. Guerin