

REGIONAL REGION  
ATLANTA  
**DUKE POWER COMPANY**  
P.O. BOX 33189  
CHARLOTTE, N.C. 28242

TELEPHONE  
(704) 373-4531

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

NOV 15 9 29 AM '82  
November 5, 1982

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Subject: McGuire Nuclear Station  
Docket No. 50-369

Reference: RII:RHA  
50-369/82-35

Dear Mr. O'Reilly:

Please find attached a response to violation 50-369/82-35-01 which was identified in IE Inspection Report 50-369/82-35. Duke Power Company does not consider any information contained in this report to be proprietary.

Very truly yours,

  
Hal B. Tucker

WHM/php  
Attachment

cc: NRC Resident Inspector  
McGuire Nuclear Station

Duke Power Company  
McGuire Nuclear Station

Response to I.E. Inspection Report 50-369/82-35

Violation 50-369/82-35-01, Severity Level V:

10 CFR 20.102(c)(1) requires that in any case where a licensee is unable to obtain reports of the individual's occupational dose for a previous complete calendar quarter, it shall be assumed that the individual has received 1.25 rems.

Contrary to the above, an exposure of 0.00 rems was credited to the individual's record for four consecutive calendar quarters when a record of the individual's exposure was not available.

Response:

1. The station agrees the violation occurred as stated.
2. The violation was due to a failure to correctly interpret supplied information concerning the individual's previous exposure.
3. The problem with the exposure folder in question was rectified.
4. Additional training has been given to those developing exposure folders and random file auditing has been initiated
5. The station is presently in full compliance with regulations in this area.