

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

22 NOV 16 P 3 : November 10, 1982

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:RCD
McGuire Nuclear Station
Docket Nos. 50-369 and 50-370
IE Bulletin 82-01, Revision 1, Supplement 1

Dear Mr. O'Reilly:

This letter is in response to IE Bulletin 82-01, Revision 1, Supplement 1. This supplement described alterations of radiographs that ITT Grinnell Industrial Piping, Inc. of Kernersville, North Carolina supplied. Twenty-six piping sub-assemblies at McGuire Units 1 and 2 were identified as containing thirty welds within the scope of this bulletin. A 100 percent review of the radiographic film has revealed that none of the film has been altered, and the required penetrameter sensitivities were clearly discernible. Acceptable weld quality has, therefore, been demonstrated.

Please advise us if there are any questions regarding this matter.

Very truly yours,

H.B. Tucker
Hal B. Tucker

WHM/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Senior Resident Inspector
McGuire Nuclear Station