



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

November 30, 1982

L. V. MAURIN  
Vice President Nuclear Operations

W3I82-0119  
Q-3-A35.07.50

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 50  
"Possible Malfunction In Agastat E7000  
Series Time-Delay Relays"

REFERENCE: LP&L Letter W3K82-0421 to USNRC dated July 15, 1982

Dear Mr. Collins:

In the above referenced letter LP&L indicated that a final report would be issued on Significant Construction Deficiency No. 50 by November 30, 1982.

At the present time all corrective actions have been taken and documentation is being assembled by the contractor for Quality Assurance review, however, additional time is necessary to complete the QA review and prepare a final report.

Therefore, the final report will be submitted by January 5, 1983.

Very truly yours,

*L. V. Maurin*  
for L. V. Maurin

LVM/WAC:keh

*IE-27*

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) E. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

4) W. Stevenson

8212140395 821130  
PDR ADOCK 05000382  
S PDR

*IE27*