FEB 2 5 1991

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear-Davis-Besse Centerior Service Company c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messers. R. A. Paul and A. G. Januska of this office on January 14 - 18, 1991, of activities at the Davis-Besse Nuclear Power Station, Unit 1 authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Messrs. Wood and Polyak and others of your staff at the conclusion of the inspection on January 18, 1991, and in subsequent telephone discussions with members of your staff between January 22 and February 22, 1991. It also refers to discussions with Mr. Polyak and others of your staff during a February 12, 1991 meeting in the Region 111 office.

The enclosed copy of our inspection report identifies areas examined during the inspection. With the areas, the inspection consisted of a selective examination of a dures and representative records, observations, and interviews and the inspection.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

TEOD

Toledo Edison Company

2 FEB 2 5 1991

We will gladly discuss any questions you have concerning this inspection.


Sincerely.


liear

L. Robert Greger, Chief Reactor Projects Branch

Enclosure: Inspection Report No. 50-346/91003(DRSS)

cc w/enclosure: L. Storz, Plant Manager OC/LFDCE Resident Inspector, RIII James W. Harris, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission





4

and Greger