

No. 2-82-32/3L

This L.E.R deals with the failure of the "B" main control room emergency ventilation fan damper. Applicable Tech. Spec. is 3.11.A.3a.

LICENSEE EVENT REPORT[illegible]