UNITED STATES



NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

JUL 1 2 1994

Dockets: 50-445 50-446 Licenses: NPF-87 NPF-89

TU Electric ATTN: W. J. Cahill, Jr., Group Vice President Nuclear Engineering and Operations Skyway Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75201

SUBJECT: NRC INSPECTION REPORT 50-445/94-13; 50-446/94-13

This refers to the inspection conducted by D. N. Graves, K. M. Kennedy, and G. E. Werner of this office on May 1-28, 1994. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The results of this inspection are documented on pages 1 and 2, in the enclosed report.

It was identified that your staff failed to follow the actions delineated in Procedure SOP-609B regarding the removal and installation of undervoltage relay fuses and this was in violation of Technical Specification 6.8.1a regarding procedure implementation. This violation is not being cited because the criteria in paragraph VII.B.2 of Appendix C to 10 CFR Part 2 of the NRC's "Rules of Practice" were satisfied.

One unresolved item was identified concerning weld cracks discovered in the Unit 2 containment spray system. This matter is discussed in Section 7 of the enclosed inspection report.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

9407190021 940712 PDR ADOCK 05000445 0 PDR

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Paner Ar A. Bill Beach, Director Division of Reactor Projects

Enclosure: Appendix - NRC Inspection Report 50-445/94-13; 50-446/94-13

cc w/enclosure: TU Electric ATTN: Roger D. Walker, Manager of Regulatory Affairs for Nuclear Engineering Organization Skyway Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75201

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, Georgia 30067-8237

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

Jorden, Schulte, and Burchette ATTN: William A. Burchette, Esq. Counsel for Tex-La Electric Cooperative of Texas 1025 Thomas Jefferson St., N.W. Washington, D.C. 20007

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L. Street, N.W. Suite 1000 Washington, D.C. 20036

Texas Department of Licensing & Regulation ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

Office of the Governor ATTN: Susan Rieff, Director Environmental Policy P.O. Box 12428 Austin, Texas 78711

JUL 1 2 1994

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IEO1)

bcc distrib. by RIV: L. J. Callan Branch Chief (DRP/B) MIS System RIV File Branch Chief (DRP/TSS)

Resident Inspector (2) Leah Tremper, OC/LFDCB, MS: MNBB 4503 DRSS-FIPB Project Engineer (DRP/B)

RIV:DRP/B	AC:DRP/B	D:DRP	
DNGraves \$	MMitter	ABBeach Mh	
1/0/94	716194	7/12/94	

180010

JUL 1 2 1994

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV: L. J. Callan Branch Chief (DRP/B) MIS System RIV File Branch Chief (DRP/TSS)

Resident Inspector (2) Leah Tremper, OC/LFDCB, MS: MNBB 4503 DRSS-FIPB Project Engineer (DRP/B)

RIV:DRP/B	AC:DRP/B	D:DRP	
DNGraves 💬	MMiTter	ABBeach IM	
1/6/94	716194	7/12/94	

-4-