John D. O'Toole Vice President Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, NY 10003 Telephone (212) 460-2533 December 5, 1982 Re: Indian Point Unit No. 2 Docket No. 50-247 LER-82-048/03L-0 Mr. Ronald C. Haynes, Regional Administrator-Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pa. 19406 Dear Mr. Haynes: The attached Licensee Event Report LER-82-048/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.a. Three copies of this letter and the attachment are enclosed as required. Whn Diffoole

attach.

cc:

Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program
Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector U. S. Nuclear Regulatory Commission P. O. Box 38
Buchanan, New York 10511