

10 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 |  
11 | The 'B' CRD AC breaker was replaced with a new breaker which was inspected and tested prior to installation. |  
12 | Inspection of the failed breaker revealed that the latch adjusting screw was improperly adjusted. This breaker |  
13 | was adjusted, tested to prove operability and returned to stores for a spare part. |

14 | |  
7 8

FACILITY STATUS		% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	2	3	4	5	6	7	8	9	10			
15	E	128	0	6	8	29	NA	30	B	31	SURVEILLANCE TEST	126
7	9	10	12	13	44	45	46	80				

ACTIVITY RELEASED		CONTENT	AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
1	2	3	4	5	6	7	8	9	10			
16	Z	133	Z	134	1	NA	35	1	NA	136		
7	9	10	11	12	13	44	45	80				

PERSONNEL EXPOSURES		NUMBER	TYPE	DESCRIPTION								
1	2	3	4	5	6	7	8	9	10			
17	0	0	0	137	Z	138	1	NA	139			
7	9	11	12	13				80				

PERSONNEL INJURIES		NUMBER	DESCRIPTION								
1	2	3	4	5	6	7	8	9	10		
18	0	0	0	140	1	NA	141				
7	9	11	12				80				

LOSS OF OR DAMAGE TO FACILITY		TYPE	DESCRIPTION									
1	2	3	4	5	6	7	8	9	10			
19	Z	142	1	NA	143							
7	9											

PUBLICITY ISSUED		DESCRIPTION		NRC USE ONLY																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
20	N	144	1	NA	145															80
7	9	10			68	69														

NAME OF PREPARER Patrick Rogers

PHONE: (501) 964-3100