MORTHEAST UTILITIES



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

December 10, 1982 MP-4464

Mr. Ronald C. Haynes Regional Administrator, Region I U. S. Nuclear Regulatory Commission Regional Office 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/82-044/03X-1

Dear Mr. Haynes:

This letter forwards Licensee Event Report 82-044/03X-1 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.a, reactor protection system instrument settings found to be less conservative than those required in the Technical Specifications but which do not prevent the fulfillment of the functional requirements of the effected system. This update corrects errors in the incident date and the report date on the previous Licensee Event Report. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E./J. Mroczka Station Superintendent Millstone Nuclear Power Station

EJM/RB:mo

Attachment: LER RO-82-044/03X-1

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30) Director, Office of Management Information and Program Control, Washington, D. C. (3)

U. S. Nuclear Regulatory Commission, c/o Document Management Branch,

Washington, D. C. 20555