



**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

November 30, 1982

L. V. MAURIN
Vice President Nuclear Operations

W3I82-0120
Q-3-A35.07.49

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 49
"Time-Trol Inc., Heat Trace Panel Malfunctions"

REFERENCE: LP&L Letter W3K82-0465 to USNRC dated July 30, 1982

Dear Mr. Collins:

The above referenced letter indicated that a final report would be submitted by November 30, 1982.

At this time corrective action to replace defective modules is still in progress, therefore, we will be unable to submit the final report until January 18, 1983.

Very truly yours,

G. D. M'London

L. V. Maurin

LVM/WAC:keh

IE-27

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) E. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) W. Stevenson

IE-27