



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

June 21, 1994

Docket Nos. 50-454, 50-455

Mr. James J. O'Connor
Chief Executive Officer
Commonwealth Edison Company
P.O. Box 767
Chicago, Illinois 60690

Dear Mr. O'Connor:

On June 7-8, 1994, NRC senior managers met to evaluate the nuclear safety performance of operating reactors, fuel facilities, and other materials licensees. The NRC conducts this meeting semiannually to determine if the safety performance of the various licensees exhibits sufficient weaknesses to warrant increased NRC attention or if it is trending adversely and requires that steps be taken to communicate concerns to the utility's president or board of directors. In addition, at this meeting, senior managers identify specific plants that have demonstrated a level of safety performance that deserves formal NRC recognition. At the January 1994 Senior Management Meeting, the Byron Station was identified as having achieved a high level of safety performance and, as a result, met criteria for recognition of its performance. I am pleased to note that Byron has again been identified as a good performer.

In identifying such plants, NRC senior managers perform an evaluation of performance in many areas including operational safety, self-assessment, problem resolution, and plant management organization and oversight.

The NRC recognizes that, to achieve the level of performance demonstrated by the Byron Station, there must be management involvement in all phases of plant activities. In addition, the staff must be dedicated, knowledgeable, and fully supportive of plant activities, and a commitment to safety must exist throughout the organization. We commend you and your staff for achieving this high level of safety performance at the Byron Station.

The greatest challenge that you now face is to maintain this level of performance and not to rest on past achievements. Continued management involvement and support, and dedicated efforts from your staff to identify and

150000

NRC FILE CENTER COPY

9407210219 940621
PDR ADOCK 05000454
P PDR

DF03/10

Mr. James J. O'Connor

- 2 -

promptly correct problems are necessary for you to continue to meet this difficult challenge.

Original signed by
James M. Taylor
James M. Taylor
Executive Director
for Operations

cc: See next page

DISTRIBUTION:

Central Files, PI-22

PDR, PI-22

RPEB R.F., O-10 A19

EDO R.F., O-17 G21

SECY, O-16 G15

OPA, O-2 G5

OCA, O-17 F2

JLMilhoan, O-17 G21

VMcCree, O-17 G21

JLieberman, O-7 H5

ESBeckjord, T-10 F12

ELJordan, T-4 D18

ACThadani, O-12 G18

GGZech, O-10 A19

LPlisco, O-12 E4

JWRoe, O-13 E4

JAZwolinski, O-13 H24

RACapra, O-13 D1

GFDick, O-13 D1

MMarkley, O-10 A19

OFC	SEND	SPS DOMIN:RIII	DD:NRR	D:NRR	EDO
NAMF	TO	JB Martin	FJ Miragli	JRUS	JMTaylor
DATE	PDR?	6/14/94	6/14/94	6/14/94	6/14/94
COPY?	Yes	No	Yes	No	Yes

OFFICIAL RECORD COPY

DOCUMENT NAME: PRIMARY.GPL / SECONDARY.GPL (merge document)

Mr. James J. O'Connor

- 3 -

cc:

Mr. William P. Poirier, Director
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355, Bay 236 West
Pittsburgh, PA 15230

Joseph Gallo
Gallo & Ross
1250 Eye St., N.W.
Suite 302
Washington, DC 20005

Michael I. Miller, Esquire
Sidley and Austin
One First National Plaza
Chicago, IL 60690

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
203 North LaSalle Street
Suite 1390
Chicago, IL 60601

U. S. Nuclear Regulatory Commission
Byron Resident Inspectors Office
4448 North German Church Road
Byron, IL 61010-9750

Ms. Lorraine Creek
Rt. 1, Box 182
Manteno, IL 60950

Chairman, Ogle County Board
Post Office Box 357
Oregon, IL 61061

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, IL 61107

Attorney General
500 South 2nd Street
Springfield, IL 62701

EIS Review Coordinator
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Chicago, IL 60604-3590

Illinois Department of Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, IL 62704

Commonwealth Edison Company
Byron Station Manager
4450 North German Church Road
Byron, IL 61010

Mr. James J. O'Connor

- 2 -

promptly correct problems are necessary for you to continue to meet this difficult challenge.

Original signed by
James M. Taylor
James M. Taylor
Executive Director
for Operations

cc: See next page

DISTRIBUTION:

Central Files, PI-22
PDR, PI-22
RPEB R.F., 0-10 A19
EDO R.F., 0-17 G21
SECY, 0-16 G15
OPA, 0-2 G5
OCA, 0-17 F2
JLMilhoan, 0-17 G21
VMcCree, 0-17 G21
JLieberman, 0-7 H5
ESBeckjord, T-10 F12
ELJordan, T-4 D18
ACThadani, 0-12 G18
GGZech, 0-10 A19
LPlisco, 0-12 E4
JWRoe, 0-13 E4
JAZwolinski, 0-13 H24
RACapra, 0-13 D1
GFDick, 0-13 D1
MMarkley, 0-10 A19

OFF	SEND	MIN:RIII	DD:NRR	D:NRR	EDO
NAME	TO	JBMartin	FJMiraglia	JRUS	JMTaylor
DATE	PDR?	6/14/94	6/14/94	6/14/94	6/12/94
COPY?	Yes	No	Yes	No	Yes

OFFICIAL RECORD COPY

DOCUMENT NAME: PRIMARY.GPL / SECONDARY.GPL (merge document)