



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • DENHAMONT, TEXAS 77704

AREA CODE 712 838 6631

December 15, 1982
RBG-13,970
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-72

On August 30, 1982, Gulf States Utilities Company (GSU) notified the Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the improper installation (torquing), testing, and inspection of concrete drilled-in-expansion-type anchors (DR-72). GSU's investigation has not been completed. An interim or final status report will be provided by February 28, 1983.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/BJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

IE-27