Dake Power Company Nuclear Production Dept P.O. Box 1007 Charlotte: N.C. 28201 1007 M.S. Turkmen Vice President Nuclear Operations (704)375-3857

ADDI

-



DUKE POWER

March 13, 1991

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 1 Docket No. 50-413 Steam Generator Inspection Report

Pursuant to Technical Specifications 3/4.4.5.5 and 6.9.2, find attached the Catawba Unit 1 End-of-Cycle 4 Refueling Outage Steam Generator Inspection Report Attachments 1, 3, 5, and 7 identify the tubes with imperfections, the imperfection location, and the size of the imperfection for Steam Generators A, B, C, and D respectively. Attachments 2, 4, 6, and 8 identify the tubes that were removed from service by plugging for Steam Generators A, B, C, and D respectively. There were 182 tubes plugged and zero tubes sleeved as a result of this inspection.

Very truly yours,

M.S. Tuckman

M. S. Tuckman

Attachments

CRL26

103200124 910

ADOCK 05000413

U. S. Nuclear Regulatory Commission March 13, 1991 Page 2

xc: Mr. S. D. Ebneter Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta St., NW, Suite 2900 Atlanta, GA 30323

> Mr. R. E. Martin Office of Nuclear Reactor Regulations U. S. Nuclear Regulatory Commission One White Flint North, Mail Stop 9H3 Washington, DC 20555

Mr. W. T. Orders NRC Resident Inspector Catawba Nuclear Station