

APPENDIX B

NOTICE OF DEVIATION

South Carolina Electric & Gas Company  
V. C. Summer

Docket No. 50-395  
License No. NPF-12

Based on the results of the NRC inspection conducted on October 1-31, 1982 certain of your activities appear to deviate from your commitments to the Commission as indicated below:

Section 5.5.15.2.1 of the Final Safety Analysis Report states that the Reactor Vessel Head Vent System has two normally deenergized valves in series in each flow path.

Contrary to the above, on October 18, 1982 the Reactor Vessel Head Vent Valves were being operated in an energized condition, in accordance with Operating Procedure 101, Reactor Coolant System.