



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

March 22, 1991

Mr. A. Bert Davis
Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Quad Cities Nuclear Power Station Units 1 and 2
Response to Inspection Report 50-254/90025;
50-265/90025
NRC Docket Nos. 50-254 and 50-265

Reference: (a) Letter from H.J. Miller to Cordell Reed
dated February 25, 1991.

(b) Telephone Conversation between B. Burgess (NRC)
and R. Rdtke (CECo) on March 4, 1991.

Mr. Davis:

The referenced letter transmitted the subject inspection report which identified a concern regarding the preparation of an out-of-service for certain Unit 1 drywell floor drain sump containment isolation valves. It was requested that an investigation into the casual factors of the errors be conducted and a written response provided. It was further stated that the out-of-service errors were similar to the errors that took place during the January 24, 1991 loss of vessel inventory event at Quad Cities Station (see Inspection Report 50-254/91006), and as such, the response could be included with the response to the issues described in Inspection Report 50-254/91006.

The telephone conversation with Bruce Burgess clarified that the response concerning the preparation of the out-of-service could be addressed with the out-of-service issues identified in Inspection Report 50-254/91006. Commonwealth Edison has reviewed this event separately and in conjunction with the January 24, 1991 event to determine the root cause and identify effective corrective actions. Regarding out-of-service personnel errors, these events are similar and, as such, will be addressed in the response to the out-of-service issues described in Inspection Report 50-254/91006.

JED
1/1

Mr. A.B. Davis

- 2 -

March 22, 1991

If your staff has any questions or comments concerning this letter, please refer them to Rita Radtke, Compliance Engineer at 708/515-7284.

Very truly yours,

T.J. Kovach
Nuclear Licensing Manager

cc: L.N. Olshan
T. Taylor, Senior Resident Inspector
NRR Document Control Desk

RR/TK/lmw