

APPENDIX A

NOTICE OF VIOLATION

Ambric Engineering, Incorporated
Philadelphia, Pennsylvania 19129

Docket No. 030-22164
License No. 37-20968-01

As a result of the inspection conducted on February 20, 1991, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

- A. 10 CFR 20.201(b) requires that each licensee make such surveys as may be necessary to comply with all sections of Part 20. As defined in 10 CFR 20.201(a), "survey" means an evaluation of the radiation hazards incident to the production, use, release, disposal, or presence of radioactive materials or other sources of radiation under a specific set of conditions.

Contrary to the above, as of February 20, 1991, adequate surveys were not performed to evaluate the exposure of an individual's film badge which indicated a radiation exposure of 1650 millirem from October 25, 1990 to November 24, 1990.

This is a Severity Level IV violation. (Supplement IV)

- B. Condition 10. of License No. 37-20968-01 requires that licensed material be stored at 4042 Ridge Avenue, Philadelphia, Pennsylvania or 1671 South DuPont Highway, Dover, Delaware, and used at temporary job sites of the licensee anywhere in the United States where the U.S. Nuclear Regulatory Commission maintains jurisdiction for regulating the use of licensed material.

Contrary to the above, as of February 20, 1991, licensed material had been stored at a temporary job site, specifically, the Sun Oil job site, for a period exceeding 6 months.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Ambric Engineering, Incorporated is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL AMBRIC - 0003.0.0
03/07/91

9104010016 910311
REG1 LIC30
37-20968-01 PDR

RETURN ORIGINAL TO
REGION I

[IE:07