

MAY 17 1994

Docket Nos. 50-352
50-353

Mr. D. M. Smith
Senior Vice President-Nuclear
PECO Energy
Nuclear Group Headquarters
Correspondence Control Desk
P.O. Box 195
Wayne, Pennsylvania 19087-0195

Dear Mr. Smith:

SUBJECT: COMBINED INSPECTION REPORT NOS. 50-352/94-11 AND 50-353/94-11

This letter transmits the results of the resident safety inspection by Messrs. N. Perry, T. Easlick, R. Nimitz and Ms. A. Wilford from March 29 through May 2, 1994 at the Limerick Generating Station, Limerick, Pennsylvania. The inspection focused on issues important to ensuring the public health and safety and consisted of observations of activities, reviews of documents, and interviews with plant personnel. The results are documented in the enclosed report and were discussed with Mr. R. Boyce of your staff at the conclusion of the inspection.

The inspectors reviewed overall licensee performance in the area of radiological controls during the 35 day Unit 1 outage and the qualifications of the new Radiation Protection Manager. In addition, the inspectors performed follow-up inspection on licensee identified matters that occurred during the outage.

The inspection identified that generally very good radiological controls were provided for outage activities. The contamination control program was effective. Two violations of your radiation protection procedures, identified by your staff, were reviewed. The first involved individuals entering onto the refueling floor without radiation work permit (RWP) prescribed dosimetry. The second involved entry of an individual into the Unit 1 drywell while signed in on the incorrect RWP. Two additional violations of technical specifications were reviewed. The first involved a missed technical specification required hourly fire watch patrol. The second involved a missed technical specification required response time test on a trip unit in the main steam line flow isolation trip logic. For all four instances, we have exercised enforcement discretion because of your identification of the events, your prompt and comprehensive corrective actions, and you met the criteria of 10 CFR 2, Appendix C, Section VII B2.

250010

9405240148 940517
PDR ADOCK 05000352
G PDR

LEO
11

MAY 17 1994

Mr. D. M. Smith

2

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Your cooperation is appreciated.

Sincerely,

ORIGINAL SIGNED BY
EDWARD C. WENZINGER

Edward C. Wenzinger, Chief
Projects Branch No. 2
Division of Reactor Projects

Enclosure: NRC Region I Inspection Report 50-352/94-11 & 50-353/94-11

MAY 17 1994

Mr. D. M. Smith

3

cc w/encl:

J. Doering, Chairman, Nuclear Review Board
D. R. Helwig, Vice President - Limerick Generating Station
G. A. Hunger, Jr., Manager - Licensing Section
J. L. Kantner, Regulatory Engineer - Limerick Generating Station
Secretary, Nuclear Committee of the Board
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
K. Abraham, PAO (2)
NRC Resident Inspector, Limerick
Commonwealth of Pennsylvania

MAY 17 1994

Mr. D. M. Smith

4

bcc w/encl:

Region I Docket Room (with concurrences)

K. Gallagher, DRP

bcc w/encl: (Via E-Mail)

V. McCree, OEDO

F. Rinaldi, NRR

C. Miller, PDI-2, NRR

M. Shannon, ILPB

D. Vito, ORA

R. Nimitz, DRS

RI:DRP

cla

CAnderson

5/16/94

RI:DRP

[Signature]
EWenzinger

5/17/95

OFFICIAL RECORD COPY

a:94119411.np

IE01