



January 27, 1983

Log No. K83-180
File: RR 2 (NP-33-82-79)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Revision 1 to Licensee Event Report 82-064. The report was revised to correct a typographical error for valve number CC1469. The revision to the report is indicated by a "1" in the left margin of the supplemental information page.

Please destroy your previous copies of this report and replace with the attached revision.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8302080136 830127
PDR ADOCK 05000346
S PDR

FEB 2 1983

IF 22