## LICENSEE EVENT REPORT

		CONTROL BLOCK:	TOR TYPE ALL REQUIRED INFORMATION
(	11	M II D C C 1 1 2 0 0 - 1 0 0 0 0 0 0 - 1 0 0	0 3 4 1 1 1 1 1 4 5 5 CAT 58
	O 1	SOURCE	
	0 2	WHILE PERFORMING AN ICE CONDENSER TOUR, AN OPERATOR DISCOVERED ONE INTERMEDIATE	
	0 3	DECK DOOR FROZEN SHUT. THIS IS NON-CONSERVATIVE WITH RESPECT TO T.S. 3.6.5.3.	
	0 4	THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.	
	0 5	THE REMAINING 191 DOORS REMAINED CLOSED AND OPERABLE.	
	0 6		
	0 7		
	0 8		
	0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE	COMP. SUBCODE SUBCODE  J X 14 Z 15 Z 16
LERINO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT NO.		CODE TYPE REVISION	
		NUMBER 21 22 23 24 26 27 28	0 3 0 0 31
$\left(\begin{array}{cccccccccccccccccccccccccccccccccccc$		TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITT	ENT NPRO-4 PRIME COMP COMPONENT MANUFACTURER  23 N 24 N 25 W 1 2 0 26
	1 0	LINE ICE WAS REMOVED AND THE DOOR WAS OPERABLE WITHIN 2 HOURS. CAREFUL EXAMINATION	
	1 1	LCOULD NOT DETERMINE THE SOURCE OF MOISTURE. SUBSEQUENT DOOR CHECKS HAVE SHOWN NO J	
	1 2	FURTHER PROBLEMS WITH ANY DOORS.	
	1 3		
	1 4		
	15	STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY NA B 31	OPERATOR OBSERVATION (32)
		RELEASED OF RELEASE AMOUNT OF ACTIVITY 35	LOCATION OF RELEASE (36)
	1 7	NUMBER TYPE DESCRIPTION 39	80
	, 8 9	PERSONNEL INJURIES NUMBER DESCRIPTION 41)	80
	1 8 9	OSS OF OR DAMAGE TO FACILITY (43)	2080326 830131
1	ाज है	TYPE DESCRIPTION (43)  [Z] (42) NA	ADOCK 05000315
(	151	PUBLICITY ISSUED _ DESCRIPTION 45	NRC USE ONLY
-	210	NA NA	68 69 80
		NAME OF PREPARER M. J. CAMP	PHONE (616) 465-5901