

Docket: 50-368

FEB 10 1983

Arkansas Power and Light Company
ATTN: William Cavanaugh III
Senior Vice President
Energy Supply
P. O. Box 551
Little Rock, Arkansas 72203

Gentlemen:

SUBJECT: IE BULLETIN 82-02 RESPONSE OF DECEMBER 31, 1982
APL NUMBER 2CAN128218

Item 4.a in your December 31, 1982, response to IE Bulletin 82-02 does not appear to address all the corrective measures required by Action Item 1 of the bulletin. Therefore, in order to evaluate your response to the bulletin adequately, please describe the actions you have taken to establish quality assurance measures for proper selection, procurement, and application of fastener lubricants and injection sealant compounds to minimize fastener susceptibility to stress-corrosion cracking environments.

A written response is requested, within 30 days of this letter, signed under oath or affirmation under provisions of Section 182a, the Atomic Energy Act of 1954. Please provide a copy to the Director, Office of Inspection and Enforcement, NRC, Washington, D.C. 20555.

Sincerely,

W. C. Seidle, Chief
Reactor Project Branch 2

cc: J. M. Levine, General Manager
Arkansas Nuclear One

8302170333 830210
PDR ADOCK 05000368
PDR
Q

1E11

OFFICE	RPS-C	RPS -C	RPB2	DDRRP&EP		
SURNAME	LJCallan:gb	WDJohnson:	WCSeidle	JEGagliardo		
DATE	02/9/83	02/9/83	02/9/83	02/9/83		

bcc to DMB (IE11)

bcc distrib. by RIV:

RPB1	Resident Inspector
TPB	Section Chief

RIV File

RA

G. Vissing, NRR

O. Lynch, NRR

ARKANSAS STATE DEPT. HEALTH