

APPENDIX A

NOTICE OF VIOLATION

Consolidated Edison Company  
Indian Point Station, Unit 2

Docket No. 50-247  
License No. DPR-26

As a result of the inspection conducted on January 10-14, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

Technical Specification 6.4, "Training," requires the retraining and replacement training program to meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971.

ANSI N18.1-1971, Section 5.5, "Retraining and Replacement Training," requires a training program to be established that maintains the proficiency of the operating organization through periodic exercises, instruction and review. Section 5.5.1, "Retraining," states that retraining should include areas such as emergency plans and security procedures, general safety, and radiation safety.

Contrary to the above, as of January 14, 1983, the licensee's general employee training program did not require periodic retraining for all plant workers in emergency plans, security procedures, general safety, and radiation safety.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Consolidated Edison Company of New York, Inc., is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY

8302180232 830204  
PDR ADOCK 05000247  
G PDR