

Springfield Bospital Wesson Memorial Bospital Wesson Women's Hospital

(1986) M6

October 13, 1931

Mr. St. Mary License Management Branch U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Your telephone request for additional information dated October 8, 1981.

Reference: MRC License #20-01412-06

Your Control #08744 dated 8/24/31

Dear Mr. St. Mary:

As per your above request the following information related to our dosimetry systems is submitted.

## Dosimetry Systems:

- 1. Electrometer: Capintec-122; SN 48E001
  Ionization Chamber: Capintec Spokas; A-12; 0.5 ml; SN 049
  Date of Calibration: November 29, 1979; Cobalt-60
  Organizatic... Regional Calibration Laboratory; New York, N.Y.
  Use: Annual and Comprehensive Calibrations
- 2. Electrometer: Victoreen-570R; SN 2417

  Ionization Chamber: Victoreen-Condenser 621; SN 2417

  Date of Calibration: May 5, 1980; Cobalt-60

  Organization: Regional Calibration Laboratory (AAPM)

  Victoreen Instruments Division

  Cleveland, Ohio 44014

  Use: Monthly and Spot-check Calibrations

NOTE: These two systems are due for calibration in 1931. The purchase orders are sent to RCL, New York and RCL, Cleveland. RCL in New York (Mr. Richard Sell) will not give an appointment for calibration unless it is an emergency!

As per RCL, New York an emergency is notice of violation from NRC for non-calibration of dosimetry system within specified period (every two years or preferably every year) To avoid any delays we are using RCL in Cleveland, Ohio. This action has increased our costs of such services.

I hope these details will help you to evaluate our compliance with condition 18 and 19 of NRC License #20-01412-06.

8302240288 830120 PDR FOIA ROSENBAU83-19 PDR



Thank you.

Sincerely,

Suresh M. Brahmavar, Ph.D.
Director, Medical Physics & Radiation Safety
Radiation Safety Officer

cc: Robert A. Grugan, M.D. Gerald A. Kerrigan, M.D.

SMB/1md