



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

February 15, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License: DPR-58
Docket No.: 50-315

Dear Mr. Keppler:

This is to confirm the verbal report given at 1309 hours on February 11, 1983, to Mr. Eric Swanson of your staff, at which time he was advised that during a routine tour, the outlet valve for the Containment Spray Additive Tank was isolated.

Investigation of this event revealed that the tank was isolated during a surveillance test seven hours previously. The valve was subsequently sealed open.

Attached to this letter is the Licensee Event Report form and Supplement, giving the details of this event and corrective action taken. According to Technical Specification 6.0, Administrative Controls, Section 6.9.1.8, Prompt Notification with Written Followup, the attached material constitutes a complete report of this event.

W.G. Smith, Jr.
W.G. Smith, Jr.
Plant Manager

/skf

cc: J.E. Dolan
R.S. Hunter
M.P. Alexich
R.W. Jurgensen
R.F. Kroeger
B. Germano
R.C. Callen MPSC
J.M. Hennigan

FEB 18 1983

8302250181 830215
PDR ADOCK 05000315
S PDR

1129

cc: (Continued)

R.O. Bruggee, EPRI

PNSRC

G. Charnoff, Esq.

E. Swanson/N. DuBry RO:III

J.F. Stietzel

E.L. Townley

Dir., I.E. (30 Copies)

Dir., MIPC (3 Copies)