TENNESSEE VALLEY AUTHORITY CHATTANOOGA, TENNESSEE 37401 1750 Chestnut Street Tower II February 18, 1983 Mr. James P. O'Reilly, Director D U.S. Nuclear Regulatory Commission 10 Office of Inspection and Enforcement Region II S 101 Marietta Street, Suite 3100 Ci Atlanta, Georgia 30303 Dear Mr. O'Reilly: TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFRO-50-259/83006 The enclosed report provides details concerning the failure of a main steam relief valve to close after being manually opened following a reactor scram. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.a(9). Very truly yours, TENNESSEE VALLEY AUTHORITY H. J. Green Director of Nuclear Fower Enclosure cc (Enclosure): Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

TE 22

8302280354 830218 PDR ADOCK 05000259 S PDR