

FEB 24 1983

Docket No. 50-346

Toledo Edison Company  
ATTN: Mr. Richard P. Crouse  
Vice President  
Nuclear  
Edison Plaza  
300 Madison Avenue  
Toledo, Ohio 43652

Gentlemen:

Thank you for your response letters dated December 10, 1982 and January 31, 1983, including our telephone conversation with R. Peters on January 5, 1983, informing us of the steps you have taken to correct the items of noncompliance. The noncompliances were brought to your attention in Inspection Report No. 50-346/82-21 forwarded by our letter dated November 3, 1982.

With respect to item 2b, we acknowledge your action taken to review the question of traceability. It is understood that your cable traceability procedures have been upgraded to include cable reel identification, and therefore, no further action is required on your part. We will examine this matter and the other noncompliances during a subsequent inspection.

Your cooperation with us is appreciated.

Sincerely,

*R. L. Spessard*  
R. L. Spessard, Director  
Division of Engineering

cc w/ltrs dtd 12/10/82 & 1/31/83:  
T. D. Murray, Station  
Superintendent  
DMB/Document Control Desk (RIDS)  
Assistant Inspector, RIII  
Harold W. Kohn, Power Siting  
Commission  
Helen W. Evans, State of Ohio

8302280392 830224  
PDR ADCK 05000346  
G PDR

1E01

OFFICE	R III	R III	R III	R III	R III	R III
SURNAME	Mendez/lc	Gardner	Williams	Jackiw	Little	Spessard
DATE	2/16/83					