System DONALD C. COOK NUCLEAR PLANT
P.O. F -x 458, Bridgman, Michigan 49106
(616) 455-5901

February 22, 1983

Mr. J.G. Keppler, Regional Administrator United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Operating License DPR-58 and DPR-74 Docket No. 50-315 and 50-316

Dear Mr. Keppler:

On February 17, 1983, we submitted a Licensee Event Report that was incorrectly numbered. This report should have been submitted as Uni 1 LER 83-001/03L-0 (previously submitted as Unit 2 LER 83-022/03L-0). An amended copy of the Licensee Event Report is attached which reflects the correct number. Would you please have this Licensee Event Report distributed to all concerned parties.

I am sorry for any inconvenience this may have caused you.

Sincerely,

W.G. Smith, Jr. Plant Manager

/bab

cc: J.E. Dolan

R.S. Hunter

M.P. Alexich

R.F. Kroeger

B. Germano

E.R. Swanson/N.E. DuBry RO: III

R.C. Callen MPSC

G. Charnoff, Esq.

J.M. Hennigan

R.O. Bruggee EPRI

INPO

PNSRC

J.F. Stietzel

E.L. Townley

Dir., IE (30 copies)

Dir., MIPC (3 copies)