

APPENDIX A  
NOTICE OF VIOLATION

Alabama Power Company  
Farley 2

Docket No. 50-364  
License No. NPF-8

As a result of the inspection conducted on November 27 - December 15, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.8.1 requires written procedures be established and implemented.

Contrary to the above, on December 6, 1982, annunciator response procedures were not followed in that the causes of two alarmed annunciators on the emergency electrical control board, annunciators Z51 and Y51, were not promptly determined and corrected as required by their alarm response procedure, FNP-O-ARP-2, Revision 2.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JAN 11 1983