

Norman W. Curtis Vice President-Engineering & Construction-Nuclear 215/770-7501

50-387

February 23, 1983

Mr. R. C. Haynes Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
CORRECTION TO INTERIM REPORT ON
DEFECTIVE GE HMA AUXILIARY RELAYS
ER 100508 FILE 821-10
PLA-1541

Reference: PLA-1528

Dear Mr. Haynes:

The referenced PLA-1528 provided the Commission with an interim report on potentially defective GE HMA Relays. When PLA-1528 was mailed to the Commission, the date was inadvertently omitted. Please note that the recorded date for PLA-1528 is February 18, 1983.

Very truly yours,

N. W. Curtis

Vice President-Engineering & Construction-Nuclear

JS:sab

8303010637 830223 PDR ADOCK 05000387 S PDR

IEZZ

February 23, 1983 - 2 - SSES PLA-1541
ER 100508 File 821-10
Mr. R. C. Haynes

cc: Mr. Richard C. DeYoung (15)

cc: Mr. Richard C. DeYoung (15)
Director-Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Gary Rhoads U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655