Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY STATION MANAGER

February 25, 1983



U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Ragion V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361 and 50-362

14-Day Follow-Up Report

Licensee Event Report No. 83-010 (Docket No. 50-361) San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter H.B. Ray (SCE) to R.H. Engelken (NRC)

dated February 14, 1983

The referenced letter provided you with confirmation of our prompt notification, pursuant to Section 6.9.1.12.b of Appendix A, Technical Specifications to Operating Licenses NPF-10 and NPF-15 for San Onofre, Units 2 and 3, involving the Control Room Emergency Air Cleanup System (CREACUS).

Pursuant to Section 6.9.1.12.b, this submittal provides the required 14-day follow-up report and a copy of Licensee Event Report (LER). Since the occurrence involves a shared system between Units 2 and 3, in accordance with NUREG-0161, a single LER 83-010 for Unit 2 (Docket No. 50-361) is provided to address this event.

If there are any questions regarding this event, please contact me.

Sincerely,

HBPay / Nimorky

Enclosure: LER 83-010

- cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)
 - R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)
 - U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement
 - U.S. Nuclear Regulatory Commission Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)