U. S. NUCLEAR REGULATORY COMMISSION VRC FORM 366 Update Report-Previous Report Date 12/16/82 Attachment to AECM-83/0135 (7.77) LICENSEE EVENT REPORT Page 1 of 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 1(1) CONTROL BLOCK: SGGS CON'T 5 | 0 | 0 | 0 | 4 | 1 | 6 | (7) | 1 | 1 | 1 | 2 | 8 | 2 | (8) | 0 | 3 | 0 | REPORT 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On November 12, 1982, fire doors 1A308 (Auxiliary Building north emergency exit) and 1 1A316 (Auxiliary Building south emergency exit) were opened to route hoses in 0 3 support of sandblasting operations in the suppression pool. An LCO was entered 0 4 I in accordance with T.S.3.7.7. The event had no effect on the health and safety of the public and did not constitute a threat to plant safety. A previous similar 0 6 report is LER 82-095/99 X-1. This is reported pursuant to T.S.3.7.7.a. 0 7 SYSTEM CAUSE CAUSE VALVE COMPONENT CODE SUBCODE Z 1 (15 Z Z | Z | Z | Z REVISION OCCURRENCE REPORT SEQUENTIAL REPORT NO. CODE TYPE NO. LER/RO 19 X REPORT 14 11 NUMBER NPRD-4 PRIME COMP SUPPLIER COMPONENT ATTACHMENT SUBMITTED MANUFACTURER HOURS FORM SUB. N (23) 0 0 0 0 N (24) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The LCO was entered to perform planned maintenance activities. The work was 1 0 completed and the doors were closed on January 10, 1983. This is submitted as | final report. 1 4 METHOD OF DISCOVERY DESCRIPTION (32) NA ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED\_OF RELEASE Z (34) NA Z (33) 1 6 80 44 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 0 37 Z 38 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 (40) NA LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION TYPE NA Z (42) 8303150254 830301 PUBLICITY PDR ADOCK NRC USE ONLY DESCRIPTION (45) N (44) NAME OF PREPARER M. Scott Freeman and Boyd Shingleton PHONE:-