Docket No. 50-87

Westinghouse Electric Corporation ATTN: Mr. G. W. Scholand, Manager Westinghouse Nuclear Training Center 505 Shiloh Boulevard Zion, IL 60099

Gentlemen:

This refers to the routine safeguards inspection conducted by Mr. T. J. Madeda of this office on February 14-15, 1983, of activities at the Westinghouse Training Reactor authorized by NRC License No. R-119 and to the discussion of our findings with Messrs. J. Snelson and F. Ellis at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, the enclosure to this letter and our report of this inspection will not be placed in the Public Document Room.

10 CFR 2.790 (d) INFORMATION

DMB: 2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. R. Miller.

J. R. Miller, Chief Materials and Safeguards Branch

Enclosure: Inspection Report No. 50-087/83-01(DRMS) (Part 2.790(d) Information)

cc w/encl:

C. Bach, Manager Instruction (Fundamentals) and Training Reactor

A. T. Sabo, Director, Licensing Safeguards & Safety

A. Joseph Nardi, Manager NES License Administration DMB/Document Control Desk (RIDS)

Madeda/jp

RIII

RIII Kill Ridgway

Miller Salas ATTAC

ATTACHMENT CONTAINS 10°CFR 2.790 (d) INFORMATION