

DMB

NRC Form 591  
(12-81)  
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION

1. LICENSEE  
Anaconda Minerals Company  
Division of Atlantic Richfield company  
R. F. D. #1, Box 79  
Tooele, Utah 84074

2. REGIONAL OFFICE  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

3. DOCKET NUMBER(S)  
030-06466

4. LICENSE NUMBER(S)  
43-07125-01

5. DATE OF INSPECTION  
January 19, 1983

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.  
**THIS IS A NOTICE OF VIOLATION** which is required to be posted in accordance with 10 CFR 19.11.
  - A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_ 10 CFR 20.203(b), (c), (d), (e) or 34.42.
  - B. Containers located in \_\_\_\_\_ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
  - C. \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ License Condition Number \_\_\_\_\_.
  - D. Records of \_\_\_\_\_ were not properly maintained. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
  - F. Reports or notifications of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - H. License condition 18 requires in part that records of calibration of portable instruments be maintained for 2 yrs. No records of calibration available for instruments.
  - I. \_\_\_\_\_
  - J. \_\_\_\_\_
  - K. \_\_\_\_\_

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This is in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

8303150353 830119  
NMS LIC30  
43-07125-01 PDR

Thomas A. Madens  
SIGNATURE - LICENSEE

1-19-83  
DATE

[Signature]  
SIGNATURE - NRC INSPECTOR

1/19/83  
DATE

IE07



INSPECTOR'S REPORT  
(Continuation)

Office of Inspection and Enforcement

03006466

NO. 8.30.1

SEQ. (A)

5177710B

7

VIOIATION SEVERITY OR DEVIATION

SITE RELATED

1	2	3	4	5	6
				✓	

A	C
B	D

VIOIATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1.

2. 10CFR 19.11(a) requires, in part, that each licensee shall post current copies of

3. specified regulations and the license or a notice specifying where such

4. documents may be examined.

5.

6. Contrary to this requirement neither the documents nor a notice were posted

7. on the employees bulletin board at the employees locker room nor were they

8. posted at the warehouse where the spare gauges were stored.

9.

10. This is a severity III level V Violation (Supplement VI, E.)

11.

12.

13.

14.

15.

16.

17.

18.

19.

20.

21.

22.

23.

24.

25.

26.

27.

28.

29.

30.

31.

32.

33.

34.

35.

48.

