

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | SCVCS | 100-0000-000 | 3 | 41000 | 4 | 5

CON'T

01 | L | 05000395 | 042083 | 052083

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | On April 20, 1983, with the Plant in Mode 5, the horizontal fire barrier above

03 | Service Water Booster Pump "A" (Intermediate Building 412') was found damaged.

04 | There were no adverse consequences due to the above noted event because the

05 | horizontal fire barrier, though damaged, continued to serve as a partial barrier.

06 | The entire area is protected by Ionization Detectors and a preaction sprinkler

07 | system which remained operative. A one (1) hour fire watch patrol was established

08 | in accordance with Action Statement (a) of Technical Specification 3.7.10.

09 | AB | A | C | ZZZZZZ | Z | Z

17 | 83 | 035 | / | 03 | L | 0 | 0

C | Z | Z | Z | 000000 | N | N | L | Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The fire barrier was apparently damaged during maintenance activities in the

11 | immediate area. The damaged barrier was replaced with a new barrier and declared

12 | operable at 0901 hours on April 22, 1983.

15 | G | 000 | N/A | A | Operator Observation

16 | Z | Z | N/A | N/A

17 | 000 | Z | N/A

18 | 000 | N/A

19 | Z | N/A

8305250349 830520
PDR ADOCK 05000395
S PDR

2C | N | N/A

L. J. Bouknight | (803) 345-5209

NAME OF PREPARER: R. J. Bouknight | PHONE: (803) 345-5209

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

May 20, 1983

83 MAY 23 AIO: 34

INPO REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 83-035

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-035 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.7.10, "Fire Rated Assemblies," on April 20, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/dwf
Attachment

cc: V. C. Summer	C. L. Ligon (NSRC)
E. H. Crews, Jr.	G. J. Braddick
T. C. Nichols, Jr.,/O. W. Dixon, Jr.	J. C. Miller
E. C. Roberts	J. L. Skolds
H. N. Cyrus	J. B. Knotts, Jr.
Group/General Managers	I&E (Washington)
O. S. Bradham	Document Management
R. B. Clary	Branch
C. A. Price	INPO Records Center
A. R. Koon	NPCF
D. A. Lavigne	File (Lic./Eng.)

OFFICIAL COPY

IE 22