




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 20, 1983

W3I83-0181
Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 55
"Hold Up and Boric Acid Make Up Tanks
Incorrect Structural Calculations"
Sixth Interim Report

REFERENCE: LP&L letter W3I83-0101 dated March 28, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 23, 1983.

At the present time, corrective action is scheduled for completion by May 31, 1983. Therefore, a Final Report will be delayed until June 21, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 3) Mr. E. L. Blake
- 4) Mr. W. M. Stevenson

8305270147 830520
PDR ADOCK 05000382
S PDR

IE275