


/ 142 DELARONDE STREET P. 0. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 20, 1983

W3183-0182 Q-3-A35.07.77

Mr. John T. Collins, Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3 Docket No. 50-382 Significant Construction Deficiency No. 77 "Inadequate Containment Purge Valves Closure Time and Flow Rate" Second Interim Report



REFERENCE: LP&L letter W3I83-0129 dated April 20, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 20, 1983.

At the present time, all hardware corrective action is complete and the supporting documentation is currently being reviewed for the Final Report. Therefore, a Final Report will be submitted by June 30, 1983.

Very truly yours,

F. J. Drummond Project Support Manager - Nuclear

FJD/MAL:keh

- cc: 1) Director 3) Mr. E. L. Blake
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555
 - 2) Director 4) Mr. W. M. Stevenson Office of Management Information and Program Control U. S. Nuclear Regulatory Commission Washington, D. C. 20555