

MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 35205

May 18, 1983

JAMES P. McGAUGHY, JR.

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Update Report - Duct Covers

Not Installed LER 82-138/99 X-1 AECM-83/0291

This is an update to a previous report submitted on December 16, 1982. The event for which the report was submitted occurred on November 12, 1982, when several duct covers were not installed because cables extending through the ducts would not allow their installation. An Limiting Condition for Operation was entered in accordance with Technical Specification 3.7.7. A Special Report was submitted pursuant to Technical Specification 6.9.2.

An engineering evaluation has determined that some barriers should be modified and others do not require modifications. Barriers requiring modification are expected to be restored by June 30, 1983. Attached is LER 82-138/99 X-1.

Yours truly,

LADole for J. P. M' bangly

JPM:sap Attachment

cc: Mr. J. B. Richard (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555 IF 22