

# RELIANCE ELECTRIC

September 7, 1982

United States Nuclear Regulatory Commission  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76011

Attention: Mr. Uldis Potapovs, Chief  
Vendor Programs Branch

Subject: Docket No. 99900761/82-01


Gentlemen:

In response to your letter of August 31, 1982, we apologize for neglecting to address the corrective action for the identified defective welds on the Texas Utilities Generating Company's Comanche Peak Shutdown Transfer Panel CP2-ECPRLV-15.

The wire remnants and weld spatter were removed and the welds corrected before the panel moved any further in the manufacturing process.

Should there be further questions, please contact me.


Sincerely,



Richard Morrow  
Manager, Quality Assurance  
for Custom Panels

RM/pm

cc: D. Roy  
J. Trivette



8209270151 820917  
PDR QA999 EMVRELIN  
99900761 PDR