



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 14, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3I82-0033
Q-3-A35.07.34

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 34
"Buffalo Forge HVAC Fan Shrouds"
Fourth Interim Report

REFERENCES: (1) LP&L Letter W3K-81-0285 dated August 10, 1981
(2) LP&L Letter W3K-82-0367 dated June 24, 1982

Dear Mr. Collins:

Due to a delay in the delivery of three (3) clips needed to correct the problem, the corrective action has not yet been completed. A final report will therefore be submitted by January 11, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

8209270155 820914
PDR ADOCK 05000382
S PDR

Mr. John T. Collins
Page 2

bcc: Ebasco (2), J. M. Brooks, R. J. Milhiser (2), F. J. Drummond,
T. F. Gerrets, C. J. Decaieaux, T. K. Armington, P. V. Prasankumar,
J. R. McGaha, J. F. Fager, Richard Hymes, L. L. Bass, M. I. Meyer,
R. W. Prados, K. R. Iyengar, J. J. Lewis, L. V. Maurin, W. M. Morgan,
G. D. McLendon, G. B. Rogers, Les Constable, Licensing Library, Central
Records