



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 14, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3I82-0032
Q-3-A35-07.40

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive
Arlington, Texas 76012


SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 40
"ITE-Gould Starter Coil Failure in Containment Cooling Fans"
Sixth Interim Report

REFERENCES: (1) LP&L Letter W3K-81-0412 dated November 17, 1981
(2) LP&L Letter W3K-82-0420 dated July 15, 1982

Dear Mr. Collins:

Six (6) of the coils in question have been returned to the vendor. LP&L will formulate a resolution on the coils and procure a disclaimer from the vendor. A final report will therefore be submitted by November 15, 1982.

Very truly yours,


L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

Mr. John T. Collins

Page 2

bcc: Ebasco (2), J. M. Brooks, R. J. Milhiser (2), F. J. Drummond,
T. F. Gerrets, C. J. Decareaux, T. K. Armington, P. V. Prasankumar,
J. R. McGaha, J. F. Fager, Richard Hymes, L. L. Bass, M. I. Meyer,
R. W. Prados, K. R. Iyengar, J. J. Lewis, L. V. Maurin, W. M. Morgan,
G. D. McLendon, G. B. Rogers, Les Constable, Licensing Library,
Central Records