

POWER & LIGHT P. D. BOX 6008 . NEW ORLEANS, LOUISIANA 70174 . (504) 366-2345

May 26, 1983

W3183-0193 Q-3-A35.07.42

Mr. John T. Collins, Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 42 R-1

"HMA Auxiliary Relays"

REFERENCE: LP&L letter W3183-0100 dated March 28, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 27, 1983.

At the present time, NCR W3-3361 is redispositioned to use the heat shrink tubing available on site. The corrective action is underway and should be completed by June 20, 1983.

Therefore, a Final Report will be submitted to the USNRC by July 17, 1983.

Very truly yours,

F. J. Drummond

Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

4) Mr. W. M. Stevenson

3) Mr. E. L. Blake

8306070274 830526 PDR ADOCK 05000382 S PDR IE-27