wo a
DN
201
B.)
75.03
HS
88
ON
710
701
~~
0
CHO
ON
OH
OH

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1982

DOCKET NO. 50-266 UNIT NAME Point Beach Unit '1 DATE September 7, 1982 COMPLETED BY C. W. Fay

TELEPHONE

414/277-2811

Io.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting 3 Down Reactor	Licensee Event Report No.	System Code4	Component Code	Cause and Corrective Action To Prevent Recurrence
4	820815	S	0	В	4	N/A	НН	нтехсн	Load reduced to complete condenser tube leak test. Five small leaks were detected and repaired in No. waterbox.

F: Forced

S: Scheduled

Reason:

- A- Equipment Failure (explain)
- B- Maintenance or Test
- C- Refueling
- D- Regulatory Restriction
- E- Operator Training & License Exam
- F- Administrative
- G- Operational Error (explain)
- H- Other (explain)

Method:

- 1- Manual
- 2- Manual Scram
 - 3- Automatic Scram
 - 4- Other (explain)

Exhibit G-Instructions for Preparation of Data Entry Sheets for LER File (NUREG-0161)

Exhibit I- Same Source

AD-28B (01 - 78)

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1982 DOCKET NO. 50-301

UNIT NAME Point Beach Unit 2

DATE September 7, 1982

COMPLETED BY C. W. Fay

414/277-2811 TELEPHONE

No.	Date	Type ¹	Duration (Hours)	Reason 2	Method of Shutting Down Reactor	Licensee Event Report No.	System Code4	Component	Cause and Corrective Action To Prevent Recurrence
4	820828	S	33.6	А	1	N/A	СВ	VALVE	Shutdown resulted from replacement of isolation valve 2-560A of reactor coolant system's RTD manifold from what is believed to be a plug stem separation.

F: Forced S: Scheduled

Reason:

A- Equipment Failure (explain)

B- Maintenance or Test

C- Refueling

D- Regulatory Restriction

E- Operator Training & License Exam

F- Administrative

G- Operational Error (explain)

H- Other (explain)

Method:

1- Manual

2 - Manual Scram

3- Automatic Scram

4- Other (explain)

Exhibit G-Instructions for Preparation of Data Entry Sheets for LER File (NUREG-0161)

Exhibit I- Same Source

AD-28B (01 - 78)