

Appendix

NOTICE OF VIOLATION

John Morrell and Company

License No. 12-15823-02

As a result of the inspection conducted on May 19, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 13 requires that chromatograph detector cells containing nickel-63 be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above requirement, your chromatograph detector cells had not been tested for leakage and/or contamination at the required intervals stated above. Specifically, your two nickel-63 detector cells source Nos. 330-0119, contained in your Perkin Elmer Gas Chromatograph, were last leak tested on December 31, 1979.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

6/9/83

for Robert A. Burgen
D. G. Weideman, Chief
Materials Radiation Protection
Section 1