FEB 23 1983

Westinghouse Electric Corporation ATTN: Mr. M. D'Amore, Manager Columbia Plant Nuclear Fuel Division Drawer R Columbia, SC 29250

Gentlemen:

SUBJECT: REPORT NO. 70-1151/83-04

This refers to the routine safeguards inspection conducted by Mr. E. L. Clay of this office on January 31 - February 4, 1983, of activities authorized by NRC License No. SNM-1107 at Westinghouse Nuclear Fuel Division and to the discussions of our findings held with Mr. B. H. Britton of your staff at the conclusion of the inspection.

Areas examined during this inspection included your program for nuclear material control and accountability under the applicable provisions of Title 10, Code of Federal Regulations, Part 70, "Special Nuclear Material," and specific license conditions. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, performance tests, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosed report with the exception of the cover page, which is an inspection summary, will not be placed in the Public Document Room

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

8303210364 830223 PDR ADDCK 07001151 PDR

J. Philip Stohr, Director Division of Emergency Preparedness and Materials Safety Programs

Enclosures: Inspection Report No. 70-1151/83-04 (Exempt from Disclosure) Westinghouse Electric Corporation

2

bcc w/encl: •
Document Management Branch
Chief of Safeguards Branch, DSRSI
Chief, Division of Safeguards
Licensing Branch, 881-SS

bcc w/o encl: License Fee Management Branch

bcc w/Inspection Summary:
State of South Carolina

RII ELClay:dr 2/23/83 GCoryell 2/25/83 RII ENAMA 2 83 JPStohr 2/23/83