

APPENDIX A

NOTICE OF VIOLATION

Boston Edison Company  
Pilgrim Nuclear Power Station

Docket No. 50-293  
License No. DPR-35

As a result of the inspection conducted on May 9-13, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violations were identified:

- A. Section 6.5.B.8.a of the PNPS Technical Specifications requires that the conformance of facility operation to provisions contained within the Technical Specifications be audited under the cognizance of the NSRAC at least once per year.

Contrary to the above, activities carried out under Sections 3.8.D and 4.8.D of the Technical Specifications were not audited from December 31, 1981 to May 13, 1983 as required.

This is a Severity Level V violation (Supplement I).

- B. Section 6.9.C.2.a of the PNPS Technical Specifications requires that a report on the radiological environmental surveillance program for the previous 12 months of operation shall be submitted to the Director of the NRC Regional Office as a separate document within 90 days after January 1 of each year.

Contrary to the above, the report for 1982 was not submitted within 90 days of January 1, 1983 as required.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Boston Edison Company is hereby required to submit to this office within 30 days of the date of this Notice a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8306280363 830613  
PDR ADDCK 05000293  
Q PDR