



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

"Public"

AUG 22 1994

Docket No. 50-456
Docket No. 50-457
License Nos. NPF-72; NPF-77

Commonwealth Edison Company
ATTN: K. Kaup, Site Vice President
Braidwood Station
RR #1, Box 84
Braceville, IL 60407

Dear Mr. Kaup:

This refers to the inspection conducted by Messrs. S. G. DuPont and E. R. Duncan of this office on June 22 through August 8, 1994. The inspection included a review of activities authorized for your Braidwood facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report, the violations were categorized at Severity Level IV and are not being cited because the criteria specified in 10 CFR Part 2, Appendix C, Section VII.B were satisfied.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Lewis F. Miller, Jr., Chief
Reactor Projects Section 1A

Enclosure: Inspection Report
No. 50-456/94020(DRP);
No. 50-457/94020(DRP)

See Attached Distribution

9408290092 940822
PDR ADDCK 05000456
Q PDR

IE01

AUG 22 1994

Docket No. 50-456
Docket No. 50-457
License Nos. NPF-72; NPF-77

Commonwealth Edison Company
ATTN: K. Kaup, Site Vice President
Braidwood Station
RR #1, Box 84
Braceville, IL 60407

Dear Mr. Kaup:

This refers to the inspection conducted by Messrs. S. G. DuPont and E. R. Duncan of this office on June 22 through August 8, 1994. The inspection included a review of activities authorized for your Braidwood facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report, the violations were categorized at Severity Level IV and are not being cited because the criteria specified in 10 CFR Part 2, Appendix C, Section VII.B were satisfied.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by Lewis F. Miller, Jr.

Lewis F. Miller, Jr., Chief
Reactor Projects Section 1A

Enclosure: Inspection Report
No. 50-456/94020(DRP);
No. 50-457/94020(DRP)

See Attached Distribution

RIII	RIII	RIII
Pirok	DuPont	Miller

AUG 22 1994

Distribution

cc w/enclosure:

J. C. Brons, Vice President,
Nuclear Support
K. Kofron, Station Manager
K. Bartes, Regulatory
Assurance Supervisor
D. Farrar, Nuclear Regulatory
Services Manager
OC/LFDCB
Resident Inspectors, Byron,
Braidwood, Zion
Richard Hubbard
Nathan Schloss, Economist
Office of the Attorney General
Licensing Project Mgr., NRR
State Liaison Officer
Chairman, Illinois Commerce
Commission
IPAS (E-Mail)

bcc: "Public"