

Yellow

JUN 28 1983

Westinghouse Electric Corporation
ATTN: Mr. W. H. Britton, Manager
Columbia Plant
Nuclear Fuel Division
Drawer R
Columbia, SC 29250

Gentlemen:

SUBJECT: REPORT NO. 70-1151/83-09

This refers to the routine safeguards inspection conducted by Mr. J. W. Sabados of this office on May 23 - 27, 1983, of activities authorized by NRC License No. SNM-1107 at Columbia facility and to the discussions of our findings held with you and members of your staff at the conclusion of the inspection.

Areas examined during this inspection included your program for nuclear material control and accountability under the applicable provisions of Title 10, Code of Federal Regulations, Part 70, "Special Nuclear Material," and specific license conditions. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, performance tests, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosed report with the exception of the cover page, which is an inspection summary, will not be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

J. Philip Stohr, Director
Division of Emergency Preparedness
and Materials Safety Programs

Enclosure: (See Page 2)

Westinghouse Electric Corporation

JUN 28 1983

Enclosures:

1. Inspection Report No. 70-1151/83-09
(Exempt from Disclosure)
2. Inspection Summary
(Not Exempt)

bcc w/Inspection Summary:
State of South Carolina

bcc w/encls:
Document Management Branch
Chief of Safeguards Branch, DSRSI
Chief, Division of Safeguards
Licensing Branch, 881SS

bcc w/o encl:
License Fee Management Branch

RII

JS [Signature]
06/27/83

RII

G [Signature]
GConyell
06/27/83

RII

EM [Signature]
EMCAT [Signature]
06/27/83

RI

JS [Signature]
JSchr
06/27/83