

USNRC REGION II
ATLANTA, GEORGIA

83 JUN 17 P2:00



June 15, 1983
L-83-360

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 1
Docket Nos. 50-335
IE Inspection Report 83-12

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Robert E. Uhrig".

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REY/PLP/js

Attachment

cc: Harold F. Reis, Esquire

8307140398 830627
PDR ADOCK 05000335
Q PDR

ATTACHMENT

ST. LUCIE UNIT 1
DOCKET NO. 50-335
IE INSPECTION REPORT 83-12

Finding

10 CFR 19.11 requires that current copies of Parts 19 and 20 of Chapter 10 to the Code of Federal Regulations, the license, and operating procedures or a document specifying where these documents may be found, and a form NRC-3 be posted wherever individuals work in or frequent any portion of a restricted area. These documents must appear in a sufficient number of places to permit individuals engaged in licensed activities to observe them on the way to or from any particular licensed activity location to which the document applies, shall be conspicuous, and shall be replaced if defaced or altered.

Contrary to the above, on April 12, 1983, documents specified in 10 CFR 19.11 were not posted at a workers' entrance to the restricted area used as an entry point into the Unit 1 containment building. Refueling and maintenance activities were in progress in the containment building at the time.

Response

1. FPL concurs with the finding.
2. Although the documents had been correctly posted, the finding occurred because they were removed by an unknown individual between March 1, 1983 and April 12, 1983.
3. As corrective action the documents were immediately replaced and posted after being made aware of the situation by the inspector.
4. To avoid further problems, the documents are now posted inside the security check point to prevent unauthorized removal.
5. Full compliance was achieved April 12, 1983.